52

DART AEROSPACE LTD

Work Order: 19665

Description: Aft Crosstube

Part Number: D2890

Drawing: D2890 Rev. B; D6008 Rev. A

Qty: 14

Page 1 of 2

Step	Location	Procedure	Ву∕	Date	Qty
1	DC	Issue Traveller  Pwg. not required RF 02.11.05	H	03.09.19	14
2	PG	Issue P/O: Loos 608  a) Extrude as per Dwg D6008 length = 180" (Ref. D6008-180) b) Material: 7075-T6/T6511 (WW-T-700/7 or QQ-A-225/9 or QQ-A-200/11) ) Seamless aluminum tube c) Minimum ultimate tensile strength = 77ksi d) Minimum tensile yield strength = 66ksi e) Material certification required	U	03-09-22	14
3	RG	Receive and inspect for transit damage Ensure material certification attached	0	of 0105	16
4	QC6	Inspect dimensions as per Dwg D6008 and check 180" length	10	04.01-13	16
5	FP	Acid etch and alodine as per QSI 005 4.1 Inside and outside of tube	1/2	04.01.13	16
6	LG	Bend as per Dwg D2890 and Folio FT002 Sign Page 2		18	1
7	QC6	Inspect dimensions per Dwg D2890 Sign Page 2	00	and a	7
8	LG	Deburr and Polish Sign Page 2	Se	let	-
9	FP	Acid etch and alodine as per QSI 005 4.1 Inside and outside of tube Sign Page 2		*	
10	QC5	Inspect work to Step 9 Sign Page 2			
11	ST	Identify and stock	DP	05/03/07	
12	AC	Cost / part: 85 4.68	Syc	05-01-21	1
13	DC	Close W/O 9/9.67 Inspect Level 21	*	05.04.25	1

Rev	Date	Change	Revised By	Approved
		New Issue, ECN 200	DM	The state of
P		Remove painting step	EC .	01
0	The second secon	Re-format; Added spec	KJ KF	LA
U	02:10.10	Me-Ioiiilat, Madod opoo		112

DELEASED OF DELEASED

725.25

DART AEROSPACE LTD	Work Order:	19665
Description: Aft Crosstube	Part Number:	D2890
Drawing: D2890 Rev. B; D6008 Rev. A	Qty:	14
	-	Page 2 of 2

W/O Step	Α	В	C	B	E	F	G	Н	ı	J	к	L
6		0-1-1-B	DP 05-2-22	DP 05-2-23			- 16					
7		Er aluli8										
8		BE =		DP 05-3-7								
9		M 2711-77		Moore	75							
10				Tokola				-		127		



